



Sunnyslope Water District

3570 Airline Highway

Phone (831) 637-4670

Hollister, California 95023-9702

Fax (831) 637-1399

BID ADDENDUM NO.1

EXCAVATION & RESTORATION FOR INSERTION VALVE

9/2/2026

Approved by:

Rob Hillebrecht, P.E.

Principal Engineer

Date: 9/2/2026

1.Introduction

This addendum forms a part of the contract documents and modifies the original bidding documents issued on August 27, 2026. All bidders must acknowledge receipt of this addendum in their bid submission. Failure to acknowledge Addendum 1 may be grounds for rejection of a bid.

2.Question Deadline

There is an inconsistency in the question deadline between page 5 and the tentative schedule in the IFB. Thus, the District wanted to correct the question deadline to September 9, 2026, at 5 PM, similar to the Tentative Schedule.

3. Bidder Questions

Date	Questioner	Question	Answer
8/28/2026	MPE	Can a map be provided with more precise location information? This will assist in both the traffic and striping replacement scope assessment	Yes, map and field photos will be provided in the Addendum #1, which will be issue on 9/2.
	MPE	There is a contradiction between the question's deadline on page 5 and the Tentative Schedule.	Question deadline is 5PM on 9/9.
8/29/2026	MPE	Will an Engineer's Estimate be provided for the bid referenced above?	We do not have a Engineer's Estimate for this project. The bid bond amount is not less than 10% of the bidder's price.
	MPE	Will you be providing Performance and Payment Bond Forms or will CAN forms be acceptable	Surety forms are acceptable.
9/1/2026	DALEO	Is there any pre-bid meeting for this work?	No, there is no pre-bid meeting for this project.

4.Map and Field Photos Added

Not-to-scale exhibits for each location are added to Addendum No.1 to support the traffic control and strip recovery descriptions provided in the IFB for better understanding and cost estimation. Estimated excavated areas are also marked in the photos.

EXHIBIT

1. Ridgemark Dr. & Pacheco Villa Ct.
(36°48'45.8"N 121°21'55.9"W)

Ridgemark Dr & Pacheco Villa Ct North and South of Valve M4/11

Valves

- Butterfly
- Gate
- Gate - Broken
- OffsetGate









2. Ridgemark Dr. & Donald Dr.
(36°48'42.4"N 121°21'56.9"W)

Ridgemark Dr & Donald Dr East of Valve M4/10. South & East Legs

Valves

- Butterfly
- Gate
- Gate - Broken
- OffsetGate







3. Donald Dr. & Rays Cir.
(36°48'47.0"N 121°22'16.3"W)

Donald Dr & Rays Cir East of Valve M4/03

- Valves
- Butterfly
 - Gate
 - Gate - Broken
 - OffsetGate





